

Navigation Database Addendum

AIRAC 2411 – Issue 8

NOTAM EP B5349/2024 effective 24th October 2024

EPCE Cewice

Runway 25, APCHs TACAN 25-X, TACAN 25-Y, TACAN 25-X and NDB 25

Due to late receipt of NOTAM, following data not updated in the FMS database:

- RWY 25 landing threshold coordinates should read **N54-25-08.14 E017-46-55.14**
- The following APCHs **do not** lead to the landing threshold
TACAN 25-X, TACAN 25-Y, TACAN 25-X, NDB 25

Navdata will be updated effective AIRAC cycle 2412.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 24th October 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2410 – Issue 16

NOTAM EP B5349/2024 effective 24th October 2024

EPCE Cewice

Runway 25, APCHs TACAN 25-X, TACAN 25-Y, TACAN 25-X and NDB 25

Due to late receipt of NOTAM, following data not updated in the FMS database:

- RWY 25 landing threshold coordinates should read **N54-25-08.14 E017-46-55.14**
- The following APCHs **do not** lead to the landing threshold
TACAN 25-X, TACAN 25-Y, TACAN 25-X, NDB 25

Navdata will be updated effective AIRAC cycle 2412.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 24th October 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com