



JEPPESSEN®

Airport Moving Map Alert

!! URGENT !!

Date: 17 November 2025

Subject: Dammam, Saudi Arabia
King Fahd Intl (OEDF)
Cycles 2511 and 2512

TWYs naming is incorrect. TWYs K1, K4, P are missing.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2511, effective 30 October 2025 and for cycle 2512, effective 27 November 2025, contain incorrect data for King Fahd Intl; Dammam, Saudi Arabia (OEDF). Saudi Arabia AIP SUP 46/25, published 14 November 2025, effective 16 November 2025, introducing “Dammam / King Fahd Intl airport - (OEDF) permanent change to Taxiway Designation”, was received after 2511 and 2512 AIRAC cycle data processing due dates.

As a result, the following changes are not reflected in cycle 2511 and 2512 data:

- TWY J (entrance to RWY 34R) is renamed to TWY J1
- TWY J1 is renamed to TWY J2
- TWY J2 is renamed to TWY J3
- TWY J3 is renamed to TWY J4
- TWY J (entrance to RWY 16L) is renamed to TWY J5
- TWY R (entrance to Apron 5) is renamed to TWY K3
- TWY K1 (entrance to Apron 8) is added
- TWY K4 (entrance to Apron 4) is added
- TWY P (between TWY P1 and TWY P2) is added

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2513, effective 25 December 2025. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

OEDF_2511_2512