



!! URGENT !!

Date: 17 November 2025

Subject: Kimberley, S Afr Rep
Kimberley (FAKM)
RNP Rwy 02
Cycle 2512

Procedure information incorrect

Jeppesen NavData for cycle 2512, effective 27 November 2025 contains incorrect data for Kimberley, S Afr Rep (FAKM).

RNP Rwy 02:

- Turn direction for holding UVKIS should read LEFT.
- Turn direction for holding ETBAB should read RIGHT.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2513, effective 25 December 2025. Please refer to the Kimberley, S Afr Rep (FAKM) chart 12-1 dated 21 NOV 25 (eff 27 Nov 25) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

FAKM_2512