



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

NAVBLUE Reference: 2512-01O

Notification Published date: 19-11-2025

Product Affected: Navigation+

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2512

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

Source: Sudan AIRAC AIP Amd 01/22

NOT IN NAVBLUE DATABASES:

Changes to the direction of the segment KAFIA-ALMAM on airway A410 due to an outstanding state query

is awaiting state information clarification.

Source: South Korea (RKPC) AIRAC AMD 06-24

NOT IN NAVBLUE DATABASES:

LPV Minima and the Path Point have not been included for RNP Y RWY 07 and RNP Y RWY 25 approaches.

is awaiting state information clarification.

Source: Canada (CYAZ) AIRAC AMD 44/24

NOT IN NAVBLUE DATABASES:

RNAV (GNSS) RWY 16 approach has not been added to NAVBLUE databases due to an issue with the CRC value (FAS Data Block).

is awaiting state information clarification.

Source: Japan (RJOI) AIP AMD 14/25

NOT IN NAVBLUE DATABASES:

RJOI RNAV (RNP) RWY 20 Approach has not been included in NAVBLUE databases due to the unavailability of the waypoint coordinates for IPMER, GURTA, LOBRY, WK001,



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

WK002, SAGPA, WK003, WK004 and PPOPS. The relevant authorities have been contacted.

is awaiting state information clarification.

Source: Bolivia (SLCB) AIRAC AIP Supplement A16/25

NOT IN NAVBLUE DATABASES:

Due to the unavailability of glide slope information the new ILS Z RWY32 approach procedure has not been added to NAVBLUE databases.

is awaiting state information clarification.

Source: USA (KVAD) FAA IFP Information Gateway

NOT IN NAVBLUE DATABASES:

The procedures for MOODY AFB (KVAD) have been withdrawn from NAVBLUE databases due to aerodrome data updates, the procedures will be made available again when the chart updates have been published.

is awaiting state information clarification.

Source: USA (KMMU) Transmittal Letter 26/25

NOT IN NAVBLUE DATABASES:

RNAV (GPS) X RWY 23 approach LPV minima has been excluded from NAVBLUE databases due to the same reference ID of RNAV (GPS) Z RWY 23 being used on the FAS DATA BLOCK (LPV), LNAV/VNAV and LNAV minima is available.

is awaiting state information clarification.

Source: Spain (LEMG) AIRAC AMD 12/25

NOT IN NAVBLUE DATABASES:

Due to an incorrect published GNSS channel on the FAS DATA BLOCK (LPV), the RNP Z RWY 13 approach procedure has not been included in the NAVBLUE databases.

is awaiting state information clarification.

Source: Turkey (LTCG) AIP 231228



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

NOT IN NAVBLUE DATABASES:

The following SIDs have not been included in NAVBLUE databases due to insufficient state information relating to the arc radials.

BAVT1M
BAVT1U
MILQ1U
PIXA1M
PIXA1U

is awaiting state information clarification.

Source: Canada (CYOO) AIRAC Canada 42/25

NOT IN NAVBLUE DATABASES:

RNAV (GNSS) RWY 23 approach LPV minima has been excluded from NAVBLUE databases due to a discrepancy with the published CRC value (FAS Data Block), LNAV minima is available.

is awaiting state information clarification.

Source: Germany (EDVE) AIRAC AMD 12/25

NOT IN NAVBLUE DATABASES:

RNP RWY 08 approach LPV minima has been excluded from NAVBLUE databases due to a discrepancy with the published CRC value (FAS Data Block), LNAV/VNAV and LNAV minima is available.

is awaiting state information clarification.