



AN AIRBUS COMPANY

## NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2512-07N

**Notification Published date:** 28-11-2025

**Product Affected:** Navigation+

**AIRAC Cycle:** 2512

**Effective Date:** 27-11-2025

**Region:** MES

**Country:** India

**Subject:** NETAJI SUBHASH CHANDRA BOSE (VECC) - ILS RWY 19R and LOC RWY 19R

**Source:** AIRAC Supp 198/25

ILS RWY 19R and LOC RWY 19R transition D345R has changed to D345O:

NETAJI SUBHASH CHANDRA BOSE (VECC)

**Please Note:** Due to a discrepancy in the state publication and after confirmation from state the following changes are required in **NAVBLUE databases**. IAF fix position has changed from D18 CEA (R-345) to D15 CEA (R-345) for the following procedures:

**Approaches ILS RWY 19R and LOC RWY 19R:**

Transition D345R has been renamed to D345O

Fix D345R has been replaced by D345O.

Co-ordinates of D345O are N22 55 05.608 E088 22 32.017