



!! URGENT !!

Date: 23 December 2022

Subject: Fes, Morocco
Saiss Intl (GMFF)
Multiple procedures
Cycle 2213

Procedure coding outdated

Jeppesen NavData for cycle 2213, effective 29 December 2022, contains incorrect data for Saiss Intl; Fes, Morocco (GMFF). AIRAC AMDT 13/22 eff 29 DEC 22 has been cancelled by NOTAM A0833/22. Below procedures should not be used:

RNAV SIDs: ATVAR 2E [ATVA2E], DEATD 1E [DETA1E], GIPUD 1E/2E [GIPU1E/2E], IVDAK 2E [IVDA2E], KEKIV 1E [KEKI1E], VAXAM 1E/2E [VAXA1E/2E]

Approach Procedures: ILS Z Rwy 27, ILS Y Rwy 27, NDB Rwy 27, VOR Rwy 27, VOR Rwy 09

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2301, effective 26 January 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

GMFF_2213