



## **!! URGENT !!**

**Date:** 24 May 2023

**Subject:** Lorient, France  
Lann-Bihoué (LFRH)  
ILS or LOC Rwy 25  
Cycle 2305

*Procedure missing from database*

Jeppesen NavData for cycle 2305, effective 18 May 2023 contains incorrect data for Lann-Bihoué; Lorient, France (LFRH). Below procedure is missing from database:

- ILS or LOC Rwy 25

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2306, effective 15 June 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Lorient, France (LFRH) 11-1 chart dated 21 JAN 22 (effective 27 Jan 2022) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.