



# **JEPPESEN<sup>®</sup>**

## ***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 22 March 2023

**Subject:** Krakow, Poland  
Balice (EPKK)  
Cycle 2303

***Apron layout incorrect***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2303 (effective 23 March 2023) contain incorrect data for Balice; Krakow, Poland (EPKK). Polish AIRAC SUP 24/23, published 23 February 2023, effective 23 March 2023, introducing “Construction Works Conducted in the Movement Area of Krakow-Balice (EPKK) Aerodrome” has been postponed per NOTAM A0575/23 and as a result, previous source AIRAC SUP 89/22 remains in force until 11 May 2023. Therefore, the following changes are not reflected in cycle 2303 data:

- TWYs Y, Z2 are withdrawn
- TWYs J, W2, S (western part) are open
- Apron (west of Stand 3) is withdrawn
- Stands 1R, 1, 1L, 2R, 2, 2L (on the new Apron) are withdrawn
- Stands 3L, 23, 24L, 24, 19 are added
- Construction area (east of Military Apron 3) is reshaped

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2304, effective 20 April 2023. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: [gjsdatasupport@boeing.com](mailto:gjsdatasupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

EPKK\_2303