



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 05 OCT 2023

Subject: Kansas City, Missouri
Kansas City Intl (KMCI)
Cycle 2310

TWY C9 and C10 names, TWY D3, Hot Spot 3, Pad B and Terminal B stands incorrect

Jeppesen Airport Moving Map and A816 formatted data for cycle 2310, effective 05 October 2023, contains incorrect data for Kansas City Intl; Kansas City, Missouri (KMCI). NFDD 179, effective 30 September 2023, introduced several changes, which are not reflected in cycle 2310 data:

- TWY C9 changed to C10
- TWY L changed to C9 (between TWY C and D)
- Removed Pad B
- Removed TWY L (between TWY D and S3)
- Added TWY D3 (between TWY D and L1)
- Revised Hot Spot 3
- Removed Terminal B Stands

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2311, effective 02 November 2023. Until then this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

KMCI_2310