

**JEPPESEN**  
***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 06 September 2023

**Subject:** Taif, Saudi Arabia  
Taif Intl (OETF)  
Cycle 2309

***RWY 17/35 status incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2309 (effective 7 September 2023) contain incorrect data for Taif Intl; Taif, Saudi Arabia (OETF). Saudi Arabia AIP SUP 17/23, effective 03 September 2023, replacing AIP SUP 14/23, effective 27 August 2023, which introduced "SWY and RESA 17: Rehabilitation for SWY and extension RESA of RWY 17" was received after 2309 AIRAC cycle data processing due date, therefore following changes are not reflected in cycle 2309 data:

Following changes are valid from 27 August 2023 until 18 November 2023:

- **RWY 17/35 is closed**
- Construction Area south of AER 35 is added

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2310, effective 05 October 2023. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: [gisdatasupport@boeing.com](mailto:gisdatasupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

OETF\_2309