



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 27 June 2023

Subject: Muscat, Oman
Muscat Intl (OOMS)
Cycle 2306

TWY A1, AP1, E1, G (east of TWY M), E3, D3 status and TWY A2, S1 name incorrect

Jeppesen Airport Moving Map and A816 formatted data for cycle 2306, effective 15 June 2023, contain incorrect data for Muscat Intl; Muscat, Oman (OOMS). Oman AIP SUP 14/2023, effective 15 June 2023, published 15 June 2023 (replacing AIP SUP 11/2023, effective 25 May 2023), introduced "Closure/Reopen of taxiways". The following changes are not reflected in cycle 2306 data:

- TWYs A1, AP1, E1, G (east of TWY M) are closed
- TWYs E3, D3 are opened
- TWY A2 is named TWY A
- TWY S1 (South of TWY V) is named TWY S

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2307, effective 13 July 2023. Until then this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

OOMS_2306