



!! URGENT !!

Date: 11 April 2024

Subject: Tulum, Mexico
Felipe Carrillo Puerto Intl (MMTL)
Multiple procedures
Cycles 2403 and 2404

Procedure coding outdated

Jeppesen NavData for cycles 2403, effective 21 March 2024 and 2404, effective 18 April 2024, contains incorrect data for Felipe Carrillo Puerto Intl; Tulum, Mexico (MMTL). MEXICO - SUP 062-24 - 28 MAR 24 - CORRIGENDUM was received after the ICAO specified date for aeronautical information publication.

For **Cycle 2403**, effective **21 March 2024**, below procedures are missing from database:

- ILS or LOC Z Rwy 12
- ILS or LOC Y Rwy 12
- VOR Rwy 12
- VOR Rwy 30

For **Cycle 2404**, effective **18 April 2024**:

ILS or LOC Rwy 12 – procedure name should read ILS or LOC Z Rwy 12

ILS or LOC Y Rwy 12 is missing from database.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2405, effective 16 May 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.