



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 18 January 2024

Subject: Grafenwoehr, Germany
Grafenwoehr AAF (ETIC)
TACAN Rwy 14
TACAN Rwy 32
Cycle 2401

Procedure Coding Unavailable & Procedure Coding Unusable

Jeppesen NavData for cycle 2313, effective 28 December 2023, and cycle 2401, effective 25 January 2024, does not have coding for the TACAN Rwy 14, and contains out-of-date information for the TACAN Rwy 32.

TACAN Rwy 14: Procedure coding is unavailable.

TACAN Rwy 32: Procedure coding is unusable.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2402, effective 22 February 2024. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site:

[Notices and Alerts.](#)

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.