

## !! URGENT !!

Date: 16 March 2023

Subject: Telluride, Colorado

> Telluride Regl (KTEX) RNAV (GPS) Z Rwy 9 **Cycles 2302 and 2303**

Missed Approach Speed Limit Missing

Jeppesen NavData for cycle 2302, effective 23 February 2023 and cycle 2303, effective March 23 2023, do not contain a speed restriction on RNAV (GPS) Z Rwy 9 missed approach coding.

The speed limit for the missed approach for RNAV (GPS) Z Rwy 9 is At or Below 180kts.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2304, effective 20 April 2023. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the Telluride, Colo (12-1) chart dated 24 JUL 20 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.