

## Navigation Database Addendum

### **AIRAC 2403 – Issue 14**

**AIP SB MAP effective 4th November 2021**

### **SBSL Sao Luis Marechal Cunha Machado Intl.**

---

#### **APCH RNP Y RWY 24**

Turn direction of MISAP HLDG at SL043 should read **left**.

Navdata will be updated effective AIRAC cycle 2404.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 20<sup>th</sup> March 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)



**Lufthansa Systems**

## Navigation Database Addendum

### **AIRAC 2402 – Issue 17**

**AIP SB MAP effective 4th November 2021**

### **SBSL Sao Luis Marechal Cunha Machado Intl.**

---

#### **APCH RNP Y RWY 24**

Turn direction of MISAP HLDG at SL043 should read **left**.

Navdata will be updated effective AIRAC cycle 2404.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 20<sup>th</sup> March 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)