

Navigation Database Addendum

AIRAC 2409 – Correction to Issue 4
other USTP/d-TPP effective 8th August 2024

KAFW Fort Worth Alliance

APCH RNAV (GPS) RWY16L/R, RNAV (GPS) RWY34R and ILS or LOC RWY 34R

For RNAV (GPS) RWY16L/R, RNAV (GPS) RWY34R:

- MISAP holding leg at OBLON should read **9NM** and speed **MAX 310KT**.

For ILS or LOC RWY 34R:

- MISAP holding speed should read **MAX 310KT**.

Navdata will be updated effective AIRAC cycle 2410.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 29th August 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2408 – Correction to Issue 17
other USTP/d-TPP effective 8th August 2024

KAFW Fort Worth Alliance

APCH RNAV (GPS) RWY16L/R, RNAV (GPS) RWY34R and ILS or LOC RWY 34R

For RNAV (GPS) RWY16L/R, RNAV (GPS) RWY34R:

- MISAP holding leg at OBLON should read **9NM** and speed **MAX 310KT**.

For ILS or LOC RWY 34R:

- MISAP holding speed should read **MAX 310KT**.

Navdata will be updated effective AIRAC cycle 2410.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 29th August 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com