



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2302-02E

Notification Published date: 20-02-2023

Product Affected: Navigation+

AIRAC Cycle: 2302

Effective Date: 23-02-2023

Region: CAN

Country: Canada

Subject: Incorrect Runway Surfaces

Source: AIRAC Canada 55/22

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2302

CAUTION: The following runways were incorrectly updated to have a soft surface type for cycle 2302. For all instances below, the correct surface type is a hard surface type.

ALTONA MUNICIPALITY, MB (CJL6) - RWY 17/35 surface type should read asphalt.

BRAMPTON-CALEDON, ON (CNC3) - RWY 08/26 and RWY 15/33 surface type should read asphalt.

BROCKVILLE REGIONAL TACKABERRY APRT, ON (CNL3) - RWY 04/22 surface type should read asphalt.

COLLINGWOOD, ON (CNY3) - RWY 13/31 surface type should read asphalt.

BIRCH HILLS, SK (CJD3) - Airport record longest runway surface should read asphalt.

These changes will be incorporated in NAVBLUE databases for cycle 2303