



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2412-03E

Notification Published date: 27-11-2024

Product Affected: Navigation+

AIRAC Cycle: 2412

Effective Date: 28-11-2024

Region: PAC

Country: Hong Kong

Subject: HONG KONG INTL (VHHH) - RNP Z RWY 25L, LOC RWY 07L/25R

Source: AIRAC Amd 11/24

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2412

HONG KONG INTL (VHHH)

CAUTION: The following discrepancies have been found in NAVBLUE databases.

RNP Z RWY 25L

The speed restriction of AT 180 kts is missing on the final approach waypoint HH815 (FAF).

Transition RIVMI altitude on the waypoint RIVMI (IF) is incorrect. The correct altitude should be between 6000-4500 ft

LOC RWY 07L

The altitude descriptor AT and Above on the final approach waypoint VH702 (FAF) is incorrect. The correct altitude should be AT 1500ft.

LOC RWY 25R -

Transition RIVMI altitude on the waypoint RIVMI (IF) is incorrect. The correct altitude should be between 6000-4800 ft

These changes will be incorporated in NAVBLUE databases for cycle 2413

