

## Navigation Database Addendum

Monday, 13 April 2026

### **AIRAC 2603 – Issue 18**

**Source: SUP 23/26, Effective date: 13 April 2026**

### **VVPC Phu Cat**

---

#### **Runway: 15**

Due to late receipt of document, RWY 15 THR displacement of 400m to the south-east is not included in database.

- RWY 15 THR coordinates should read **N13-57-48.30 E109-02-11.80**.
- All approach procedures to RWY 15 are temporarily suspended.
- Declared distances should read
  - RWY 15 TORA 2648 m TODA 2948 m ASDA 2788 m LDA NIL
  - RWY 33 TORA 2648 m TODA 2948 m ASDA 2788 m LDA 2648 m

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)

## Navigation Database Addendum

Monday, 13 April 2026

### **AIRAC 2604 – Issue 9**

**Source: SUP 23/26, Effective date: 13 April 2026**

### **VVPC Phu Cat**

---

#### **Runway: 15**

Due to late receipt of document, RWY 15 THR displacement of 400m to the south-east is not included in database.

- RWY 15 THR coordinates should read **N13-57-48.30 E109-02-11.80**.
- All approach procedures to RWY 15 are temporarily suspended.
- Declared distances should read
  - RWY 15 TORA 2648 m TODA 2948 m ASDA 2788 m LDA NIL
  - RWY 33 TORA 2648 m TODA 2948 m ASDA 2788 m LDA 2648 m

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)