

## !! URGENT !!

Date: 07 November 2025

Subject: Ili, PR Of China

Yining (ZWYN) Multiple procedures Cycles 2511&2512

Procedures information incorrect

Jeppesen NavData for cycle 2511, effective 30 October 2025 for cycle 2512, effective 27 November 2025 contains incorrect data for Yining; Ili, PR Of China (ZWYN). AIP SUP 007-25 effective 30 March 2025 has been cancelled and replaced by AIP SUP 024-25 effective 20 October 2025, which was published after the ICAO specified date for aeronautical information publication.

The following procedures should not be used:

STARs: P165 01A [P1601A], P165 11A [P1611A]

• SIDs: P165 01D [P1601D], P165 02D [P1602D], P165 11D [P1611D]

The following procedure is missing from the database:

- STARs: P178 A6 [P178A6], P178 A9 [P178A9]
- SIDs: P178 D6 [P178D6], P178 D9 [P178D9]

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2513, effective 25 December 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.