



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2512-05E

Notification Published date: 24-11-2025

Product Affected: Navigation+

AIRAC Cycle: 2512

Effective Date: 27-11-2025

Region: MES

Country: India

Subject: SARDAR VALLABHBHAI PATEL INTL (VAAH) - VOR RWY 05 Approach

Source: AIRAC Supp 55-25

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2512

SARDAR VALLABHBHAI PATEL INTL (VAAH)

CAUTION: VOR RWY 05 approach transition D229L contains an incorrect speed in NAVBLUE databases. The D229L fix speed restriction MAX 180kts is incorrect and should be disregarded.

These changes will be incorporated in NAVBLUE databases for cycle 2513