

Navigation Database Addendum

Monday, 29 September 2025

AIRAC 2510 – Issue 7

Source: SUP, Title: FZ 04/2024, Effective date: 25.01.2024

FZIC Bangoka Intl

Runway: 12

RWY 12 temporarily displaced by 750m.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews.

Lufthansa Systems FMS Customer Support

All valid NDAs are available on https://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com



Navigation Database Addendum

Monday, 29 September 2025

AIRAC 2511 – Issue 1

Source: SUP, Title: FZ 04/2024, Effective date: 25.01.2024

FZIC Bangoka Intl

Runway: 12

RWY 12 temporarily displaced by **750m**.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews.

Lufthansa Systems FMS Customer Support

All valid NDAs are available on https://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com