



!! URGENT !!

Date: 07 June 2023

Subject: Phu Yen, Vietnam
Tuy Hoa (VVTH)
Multiple procedures
Cycle 2306

Procedures missing from database

Jeppesen NavData for cycle 2306, effective 15 June 2023, contains incorrect data for Tuy Hoa; Phu Yen, Vietnam (VVTH). NOTAM C0239/23 extending validity of DAP SUP C27/22 was received after the ICAO specified date for aeronautical information publication.

Below procedures are missing from database:

STAR Procedures: **KAMGO 1M** and **KARAN 1G**

Instrument Approach Procedures: **RNP Z Rwy 03** and **RNP Y Rwy 03**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2307, effective 13 July 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Phu Yen, Vietnam (VVTH) 10-2-0, 12-1-0 and 12-2-0 charts dated 6 JAN 23 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VVTH_2306