



# **JEPPESEN<sup>®</sup>**

## ***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 02 February 2023

**Subject:** Malabo, Eq Guinea  
Malabo (FGSL)  
Cycle 2301

***TWY D status incorrect***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2301 (effective 26 January 2023) contain incorrect data for Malabo; Malabo, Eq Guinea (FGSL). ASECNA AIP SUP 08/A/23FC, effective 31 January 2023, was received after the ICAO specified date for aeronautical information publication and as a result, changes indicated in the AIP SUP 08/A/23FC, could not be applied on time.

Incorrectly depicted as open and should be **closed**:

- **TWY D**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2302, effective 23 February 2023. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: [GISDataSupport@boeing.com](mailto:GISDataSupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.