



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 05 December 2024

**Subject: Addis Ababa, Ethiopia
Bole Intl (HAAB)
Cycle 2412**

TWY Q and Parking Stands H1, H2 missing

Jeppesen Airport Moving Map and A816 formatted data for cycle 2412, effective 28 November 2024, contain incorrect data for Bole Intl; Addis Ababa, Ethiopia (HAAB). Ethiopia AIRAC AIP SUP 04/24, effective 28 November 2024, introducing new Aircraft Parking/Docking Chart, was received after 2412 AIRAC cycle data processing due date, therefore the following changes are not reflected in cycle 2412 data:

- TWY Q (between TWY G and GA Apron) is added
- Parking Stands H1, H2 (west of Parking Stand N1) are added
- Parking Stands N19- N23 are updated
- Parking Stands N24, N25 are removed

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2413, effective 26 December 2024. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.