



# **JEPPESEN®**

## ***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 15 November 2023

**Subject:** Lyon, France  
Saint Exupery (LFLL)  
Cycle 2311

***RWY 17R/35L and TWYs A1, A2, A3, A5, TA and T status incorrect***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2311, effective 02 November 2023, contain incorrect data for Saint Exupery, Lyon; France (LFLL).

The following changes, effective 02 November 2023, are not reflected in cycle 2311 data:

- RWY 17R/35L is open
- TWYs A1, A2, A3, A5 and TA are open
- TWY T (between TWYs A1 and TN1) is open
- TWY T (between TWYs TN3 and TB) is open

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2312, effective 30 November 2023. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: [GISDataSupport@boeing.com](mailto:GISDataSupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

LFLL\_2311