



JEPPesen®

Airport Moving Map Alert

!! URGENT !!

Date: 21 September 2023

Subject: Muscat, Oman
Muscat Intl (OOMS)
Cycle 2309

TWYs E2, E3, E4, D2, D3, D5, F status incorrect. TWYs A1, B, C, D6, D7 names incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2309, effective 07 September 2023, contain incorrect data for Muscat Intl; Muscat, Oman (OOMS). Oman AIP SUP 40/23, published 20 September 2023, effective 19 September 2023, introduced "Closure/Reopen of Taxiways". The following changes are not reflected in cycle 2309 data:

Following changes are valid from 12:00 on 19 September 2023 until 23:59 on 04 October 2023:

- Renamed TWY A1 to D1, C to D5, B to D6, D6 to D7, D7 to D9
- TWYs E3, D3 are closed
- TWY F (between TWYs D2 and E4) is closed
- TWY F (between TWYs E2 and D2, between TWYs E4 and E5) is open
- TWYs E2, E4, D2, D5 (former TWY C) are open

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2310, effective 05 October 2023. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

OOMS_2309