



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 26 March 2024

Subject: Hanoi, Vietnam
No Bai Intl (VVNB)
Cycle 2403

Stands 30A, 31A, 32A, 33A, 34A, 34B, TWY W2A, TWY W2 extension missing.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2403, effective 21 March 2024 contain incorrect data for No Bai Intl; Hanoi, Vietnam (VVNB). SUP 11-24, published 06 March 2024, effective 06 March 2024 introducing “Put into operation a portion of the eastern extended Apron T2 at No Bai International Airport (VVNB)”, was received after 2403 AIRAC cycle data processing due date. Therefore, following changes (effective 06 March 2024) are not reflected in cycle 2403 data:

- Stands 30A, 31A, 32A, 33A, 34A, 34B added
- TWY W2A added
- TWY W2 extension added

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2404, effective 18 April 2024. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

VVNB_2403