



Lufthansa Systems

Navigation Database Addendum

AIRAC 2303 – Issue 13

SUP DAP C26/22 effective 29th December 2022

VVPC Binh Dinh Phu cat

Runway 33

Effective 23th March 2023 until 29th March 2023

- RWY 33 landing threshold **temporarily displaced by 720m**.
- All APCH procedures are **invalid**, except VOR X 33 and VOR W 33 APCH.
- VOR X 33 and VOR W 33 APCH **do not lead** to the displaced landing threshold, vertical guidance **should not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 22nd March 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com