

Navigation Database Addendum

AIRAC 2402 – Issue 4

NOTAM A0199/24 effective 29th January 2024

LGKR Kerkira Ioannis Kapodistrias

Runway 34

At LGKR first 563 meters from the beginning of runway 34 closed due to work in progress.

The NavDB **does NOT reflect** the temporary displacement.

DECLARED DISTANCES:

RWY 16: TORA 1810M TODA 1810M ASDA 1810M LDA 1400M

RWY 34: TORA 1810M TODA 1810M ASDA 1810M LDA 1810M

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 5th February 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2401 – Issue 9

NOTAM A0199/24 effective 29th January 2024

LGKR Kerkira Ioannis Kapodistrias

Runway 34

At LGKR first 563 meters from the beginning of runway 34 closed due to work in progress.

The NavDB **does NOT reflect** the temporary displacement.

DECLARED DISTANCES:

RWY 16: TORA 1810M TODA 1810M ASDA 1810M LDA 1400M

RWY 34: TORA 1810M TODA 1810M ASDA 1810M LDA 1810M

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 5th February 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com