

Navigation Database Addendum

AIRAC 2403 – Issue 11

SUP S04/24 effective 22nd February 2024

LIBP Pescara

Runway 04/22

From 22 February 2024 runway extension works will take place.
Works are divided into four phases that will be activated by Notam.

Phases 1, 2, 3:

- RWY length 2214 (m)
- Coordinates THR RWY 04 N42 25 26.59 / E014 10 31.81
- THR Elevation RWY 04 45.3ft and Aerodrome Elevation 45ft
- Take off RWY 22, landing RWY 04 and intersection take off B forbidden.
- ILS not available
- SIDs RWY 22 suspended
- Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

| | TORA (m) | TODA(m) | ASDA(m) | LDA (m) |
|-------------------------|----------|---------|---------|---------------|
| RW04 | 2214 | 2214 | 2214 | not available |
| Intersection take off C | 1625 | 1625 | 1625 | not available |

| | TORA (m) | TODA(m) | ASDA(m) | LDA (m) |
|------|---------------|---------------|---------------|---------|
| RW22 | not available | not available | not available | 2026 |

Phase 4:

- ILS/DME RWY 22 operating with new ident IPSC
- New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 15th March 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com