

Navigation Database Addendum

AIRAC 2403 – Issue 13

LECM Madrid FIR; LECB Barcelona FIR

AWY T100

AWY T100 is **missing** in database.

T100 routing should read:

ORTOP – TUTIS – TAVSI – XULIM – AMPIR – SOVIS – GOSOS – GONZA – GOLFO – MIMDI – RINDI – XENVO – PIDUD – PIMAD – XARON – XESPA – MAMOM – SOTAX

Navdata will be updated effective AIRAC cycle 2404.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 19th March 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com