

Navigation Database Addendum

AIRAC 2404 – Issue 7

LQ SUP 006/2023 effective 10th August 2023

LQMO Mostar / Ortijes

Waypoint MO425

Coordinates of waypoint MO425 should read **N43-30.9 E017-44.4** (N43° 30' 56.685" E017° 44' 21.973") instead of N43-30.9 E017-44.9 (N43° 30' 56.685" E017° 44' 54.916")

Navdata will be updated effective AIRAC cycle 2405.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 12th April 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2403 – Issue 26

LQ SUP 006/2023 effective 10th August 2023

LQMO Mostar / Ortijes

Waypoint MO425

Coordinates of waypoint MO425 should read **N43-30.9 E017-44.4** (N43° 30' 56.685" E017° 44' 21.973") instead of N43-30.9 E017-44.9 (N43° 30' 56.685" E017° 44' 54.916")

Navdata will be updated effective AIRAC cycle 2405.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 12th April 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com