



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2302-03E

Notification Published date: 01-03-2023

Product Affected: Navigation+

AIRAC Cycle: 2302

Effective Date: 23-02-2023

Region: EUR

Country: Austria

Subject: WIEN SCHWECHAT (LOWW) - VOR RWY 16 & 34 Transitions

Source: AIP 230224

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2302

WIEN SCHWECHAT (LOWW)

CAUTION: The following VOR transition idents are incorrect in **NAVBLUE** databases:

VOR RWY 16 - BAL5L, MAB6L, NER6L, PES5L

VOR RWY 34 - BAL3N, MAB4N, NER4N, PES4N

The correct idents are as follows:

VOR RWY 16 - BAL6L, MAB7L, NER7L, PES6L

VOR RWY 34 - BAL4N, MAB5N, NER5N, PES5N

CAUTION: The following VOR transitions have missing speed restrictions:

VOR RWY 16 -

BAL6L WW676 230kts MAX, MAB7L WW676 230kts MAX, NER7L WW677 230kts MAX,
PES6L WW676 230kts MAX

VOR RWY 34 -

BAL4N WW978 230kts MAX, MAB5N WW977 230kts MAX, NER5N WW977 230kts
MAX, PES5N WW977 230kts MAX

These changes will be incorporated in NAVBLUE databases for cycle 2303