



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2303-02E

Notification Published date: 22-03-2023

Product Affected: Navigation+

AIRAC Cycle: 2303

Effective Date: 23-03-2023

Region: EEU

Country: China

Subject: SHENZHEN/BAOAN (ZGSZ)

Source: AIP Amd 03/23

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2303

SHENZHEN/BAOAN (ZGSZ)

CAUTION: RNP ILS/DME Z RWY15 missed approach is incorrect in **NAVBLUE** databases. The missed approach course to GLN (after D6.5 IQJ) should be 32° instead of 37°.

CAUTION: ILS/DME Y RWY33 transition D245R is incorrect in **NAVBLUE** databases. The fix D245D should not be used. The correct fix should be D245B (N22 28 45.598 E113 52 06.272).

These changes will be incorporated in NAVBLUE databases for cycle 2304